
	!	
	5	
	Accident No. U.S. Date	
-	1 - 4	•
	Analyzed by Analyzed by	
	Copied for Wright	
	Field by	
	Notes On the second of the sec	•
*	- argent	
		-
	of Theth	
	(Nature Group	
	(Specific Nature	
	(Specific Nature Polat for the transmit that	1
	(Underlying Nature	
	(Cause Group 75% Ausport	
. 4	(8) Inherent	
100	(Stepheng Course Hayandows opposition	
* #	11-259, PE. Judgment to efficiency	
	13 100000000000000000000000000000000000	
	17 Fact of care in lake off	
2000		
Sample of		
arran a		
į.		
		Andrew Marie Control



DESCRIPTION OF ACCIDENT (Brief narrative of accident. Include statement of responsibility and recommendations for action to prevent repetition) Aircraft hit obstruction light with mose wheel during take off. Upon inspection light was found to be too close to end of runway oreating a hazard. Lights have since been soved. · Recommendations: Hone. Date July 17, 1943

573RD BOMBARDMENT SQUADRON (M) AAF Office of the Operations Officer Myrtle Beach, South Carolina

June 1, 1943.

SUBJECT: Report of Damage and Personnel Involved.

TO: Operations Officer, 391st Bombardment Group (M) AAF, Myrtle Beach Range, South Carolina.

1. Extent of damage to aircraft No 41-31759 received in take-off at 0825, June 1, 1943.

a) Nose wheel.

b) Nose wheel acturating cylinder brace.

c) Aft left half bomb bay door beyond repair.

d) 12" rip in bulkhead behind aft left bomb bay door.

e) Rivet lost above bomb bay door aft fuselage.

2. The aircraft will be out of commission for approximately one (1) week.

3. Personnel in aircraft:

P	2nd Lt. Porter, H. D.	0-731656
CP	2nd Lt. Stokes, M. R.	0-796906
BN	2nd Lt. Williams, B. E.	0-733244
EG	S/Sgt. Reib, C. O.	33270439
RG	S/Sgt. Grace, T. H.	34331037
-	Sgt. Sanders. G. B.	35303680

4. Pilot's Statement:

While taking off west on east-west runway at Myrtle Beach Bombing Range, at full power of 50" of Hg and 2650 R.P.M., in airplant model B-26 B20, AAF Serial No 41-31759, the airplane collided with a light post at the end of the runway, causing damage to the aircraft with no injury to the crew. The damage is listed with this report, by the Squadron Engineering Officer.

HARRY D. PORTER, 2nd Lt., Air Corps, Pilot, 573rd Bomb Sq. 573RD BOMB ROMENT SQUADRON (M) AAF Office of the Operations Officer. Myrtle Beach, South Carolina

June 1, 1943.

SUBJECT: Damage on Airplane B-26 B20 Serial No 41-31759.

TO: 573rd Bombardment Squadron (M), Office of the perations Officer, Myrtle Beach, South Carolina.

- 1. A visual check immediately after emergency landing of the above airplane disclosed the following damage:
 - a. Nosewheel tire and tubing blown and rim cracked.
 - b. Nosewheel actuating cylinder bulkhead brace wrinkled.
 - c. Left aft bomb bay door damaged beyond repair.
- d. Bulkhe d behind aft bomb bay doors has a tear approximately twelve inches in diameter.
- e. One rivet thrown from left fuselage skin above bomb bay door.
- 2. Estimated time for necessary repairs ap roximately one (1) week.

William Co CORRELL, WILLIAM Co. CORRELL, 2nd Lt., Air Corps, Engineering Officer.

HEADQUARTERS MYRTLE BEACH BOMBING RANGE RSA/JAT/ebg Myrtle Beach, South Carolina July 27, 1943 SUBJECT: Report of Aircraft Accident. Headquarters, Flight Control Command, Army Air Forces, Winston-Salem, North Carolina. 1. Inclosed, herewith, Form 14, Accident Report. JOHN A. TARRO Commanding 3 Incls: Incl 1 - AAF Form 14.
Incl 2 - Statement of Pilot. Incl 3 - Statement of Gp. Engineering Officer -1-