WAR DEPARTMENT

U. S. ARMY AIR FORCES REPORT OF AIRCRAFT ACCIDENT

(1) Place ...AAB, JAAF, JACKSONVILLE, FLA.... (2) Date ... 14 December 1943 Type and model B-26C (5) A. F. No.41-34799 (6) Station Godman Field Organization: (7) 3rd B.C. 3rd AF (8) 391st Bomb (11) (9) 574th Bombardment Some (Boundary of Company of Com AIRCRAFT: (4) Type and model B-26C PERSONNEL A (Lest name first) Dura RATINO SERIAL NO. RANK PERSONNEL AIR FORCE OR COMMAND (10) (12) (14) (15) (16) (17) (18) P Matelsky, Peter (-01 3rd DUCP. Dietachler, Elmer A CP. 01 3rd Shupenke, Anthony (-) T 3rd Jenkins, William B., Jr. Little, Joseph R. Forster, William J AG Ramos, Salvador (-) X Halpin, William M. AG 32449879 (20) Motelaky, (23) Ol (24) Air Corps Attached for flying (29) Third (\$1) 574th B (34) 1-2-43... Present rating (35) .Pilot (30)1-2-43.... Instrument rating (37) .8-27-43 Original rating (33) Pilot -10-44 FIRST PILOT HOURS: (at the time of this accident) (38) This type187:00 (43) Instrument time last 6 mont 33:00 (39) This model. 138200 ... (43) Instrument time last 30 days. (40) Last 90 days ... 114:00 ... (44) Night time last 6 months. (41) Total (45) Night time last 30 days. AIRCRAFT DAMAGE DAMAGE (49) LIST OF DAMAGED PARTS (46) Aircraft. Left Wing Tip Q.K. (47) Engine(s)... (48) Propeller(a) QaKa 1 (50) Weather at the time of accident ... High thin scattered. ... Vis. unrestricted. Winds NHE 11 mph (51) Was the pilot flying on instruments at the time of accident . No. (83) To Myrtle Beach, S. C. (84) Kind of charance ... Instrus Cleared from Fort Know (56) Nature of accident . Taxiing (87) Cause of sceiders .Taxiing behind parked B-25 on rasp without properly checking for

RESTRICTED

DESCRIPTION OF ACCIDENT

(Brief narrative of accident. Include statement of responsibility and recommendations for action to prevent repetition)

On the night of 14 December 1943, at approximately 1845 EWT, a B-26 piloted by 2nd Lt Peter Metelsky collised with a parked B-25 airphane on the transient hanger line. Bad weather further south of the terminal and heavy traffics resulted in Jacksonville. Lack of personnel prevented the line crew form guarding each wing tip of parked and taxiing planes.

It is evident that the pilot saw the B-25 parked on the line as he states that he did not think he was that close. It is the opinion of the committe that subject pilot was taxing too fast and that uncertain as to the exact position of other aircraft and should have stopped before taxing on.

FINDINGS:

It is the epinion of this commettee after having investigated the accident that:

- (1) The pilot was taxiing too fast on the ramp where other airplanes were parked. Damage to B-25 reveals that it was struck with a great force to cause resultant damage.
 - (2) Pilot error.

IT IS RECOMMENDED THAT:

(1) Pilote use more caution in taxiing among parked planes.



CONTRACTORS CORE LES AG.

ACCIDENT No. .

WAR DEPARTMENT

U. S. ARMY AIR FORCES

REPORT OF AIRCRAFT ACCIDENT

Organization: (7)	(Command and A)	r Forces (8)	PRO ISTORY) Station HUNTER FIEID, GA. (Squastron)						
	-	and the same of th	PARTIE STATE	Total Control of the	and or to the same	· contraction	er codminum	performan		
DUTY NAME (Last name first)	RATING	SERIAL NO.	RANE	PERSONNEL CLASS	BRANCH	AM PORCE OR COMMAND	RESCUT TO	Can ou Panacity		
(10) (11)	(19)	(13)	(14)	(15)	(10)	(17)	PERSONNEL (183)	(10)		
Rimmer, Fred E.		*************		-		- House to the same	AND DESCRIPTION OF THE PARTY OF	-		
Transfer Dr.			-							
and a second and a	the said	and the same of th	1	-			***********			
		- 2-	V	1		- exclusion and				
The second secon		CENT	1	1		THE STREET	Carlo de la companio del la companio de la companio del la companio de la compani	-		
	f 1 4	Mary Villagery D.	-	J						
The state of the s	121 44	Constitution.	1		THE PROPERTY AND ADDRESS.		CONTRACTOR STORES			
	11/2	En	-		*******	CONTRACTOR	COLUMN DESIGNATION OF THE PERSON OF THE PERS	-		
	Till !	- San 363	Jan St.	THE RESERVE	DESCRIPTION OF THE PARTY OF	Carrier and Carrie	TOTAL TOTAL COMM	France		
	1.73	Salema Marie	·	-	Chemistry of the Asia		-			
	100	HETTER	Kanna		-		-			
		PILOT CHAP	IGED WITH	ACCIDINT						
(Last meno) (First manus)	Offstow to	(21)		(22)		(Personnel ti	(34)			
						O'mentured of	MEG .	(Dranch)		
seigned (25)(Consumi and Air For	ros) (26)	(Green)	(97)	Citylesides		(25)	(Station)			
		178	(94)			180				
riginal rating (88)(Samp) (84)	ant Ad Formi Death		No. Chartesp	(36)(Eni		iment rating ((90000)	(Date)		
riginal rating (88) (86) (86)		resent rating ()	(42) (43) (44) (45)	fastrament t Instrument t Night time i	lime last 6 n		(Platent)	(District)		
reginal rating (88)		resent rating ()	(42) (43) (44)	fastrument t Instrument t Night time h	lime last 6 n time last 30 net 6 month net 30 days.	nonths	(Platent)	(Distr)		
Original rating (SS) (Sound) Court Piter House: at the time of this accident) (SS) This type. (SS) This model. (40) Last 90 days. (41) Total. DAMAGE		AIRC	(42) (43) (43) (43) RAFT DAMA	fastrument i Instrument i Night time i Night time i	lime last 6 n lime last 6 n sime last 30 ast 6 month ast 30 days.	nonths	(0100000)			
rast Piter House: at the time of this accident) (38) This type. (39) This model. (40) Last 90 days. (41) Total.		AIRC	(42) (43) (44) (44) (45) RAPT DAMA	fastrument i Instrument i Night time i Night time i GE (40) Li	lime last 6 milime last 30 month ast 30 days.	ment rating (nonths	ical Sta	bilise		
Original rating (33)	(Date)	AIRC	(42) (43) (44) (44) (45) RAPT DAMA	fastrument i Instrument i Night time i Night time i GE (40) Li , Right in	lime last 6 milime last 30 month ast 30 days.	ment rating (nonths	ical Sta	bilise		
reginal rating (88) (36) (more Prior House: at the time of this accident) (38) This type. (39) This model. (40) Last 90 days. (41) Total DAMAGE (5) Propeller(s) 1 1 (6) Weather at the time of accidents (5) Was the pilot flying on instruction	(Date) Pr	AIRC Lef (A)	(42) (43) (44) (45) RAFT DAMA t. Rudder, t. Slevate	Instrument t Instrument t Night time h Night time h GE (40) Li , Right B or, Horis	lime last 6 m time last 30 ast 6 month ast 30 days.	ment rating (nonths	ical Sta	bilise		
reginal rating (88) (Seeing) (84) (Inser Pitter Horna: at the time of this acrident) (38) This type. (39) This model. (40) Last 90 days. (41) Total. DAMAGE DAMAGE O Weather at the time of seciols	(Date) Pr	AIRC Lef (A)	(42) (43) (44) (45) RAFT DAMA t. Rudder, t. Slevate	Instrument t Instrument t Night time h Night time h GE (40) Li , Right B or, Horis	lime last 6 m time last 30 ast 6 month ast 30 days.	ment rating (nonths	ical Sta	bilise		
riginal rating (88) (10sing) (10sin	t 3	AIRC Lef (A)	(42) (43) (44) (45) RAFT DAMA t. Rudder, t. Slevate	Instrument t Instrument t Night time h Night time h GE (40) Li , Right B or, Horis	lime last 6 m time last 30 ast 6 month ast 30 days.	ment rating (nonths	ical Sta	bilise		
riginal rating (88) (10sing) (84) (10sing) (84) (10sing)	Contact by Contact of the time (54)	AIRC Lef (A)	(42) (43) (44) (45) RAFT DAMA t. Rudder, t. Slevate l. panels	Instrument t Instrument t Night time h Night time h GE (40) Li , Right B or, Horis	lime last 6 m time last 30 ast 6 month ast 30 days.	ment rating (nonths	ical Sta	bilise		
riginal rating (88)	Contact by Contact of the time (54)	AIRC Lef (A)	(42) (43) (44) (45) RAFT DAMA t. Rudder, t. Slevate l. panels	Instrument t Instrument t Night time h Night time h GE (40) Li , Right B or, Horis	lime last 6 m time last 30 ast 6 month ast 30 days.	ment rating (nonths	ical Sta	bilis		
riginal rating (88)	t 3 (68)	AIRC Laf (A)	(42) (43) (44) (45) RAFT DAMA t. Rudder, t. Slevate l. panels	Instrument t Instrument t Night time h Night time h GE (40) Li , Right B or, Horis	lime last 6 m time last 30 ast 6 month ast 30 days.	ment rating (nonths	ical Sta	bilise		

Inol #2

-				391st Bomb (M)		AIR	CRAFT MODEL		
_2	ODERICE D. SEAL " TYSET "	574 th Bomb (M)		41-34799					
CRIS.	- PRINT PLAINLY	ALWAYS		FLIGHT DATA					
1 .	NAME - RANK - ORGANIZATION	DIRECTED LOCALLY	ENTE	ENTER DUTY SYMBOLS ENTER N - NIGHT OR I - R TIME FLOWN THE	REUNDER	-	TA		
	574th Godson Fld	-	-	5 9077 N 081 DUTY NO	T T	N RECEIPTION	AND MISSION	SECTION AND ADDRESS OF THE PARTY.	
-	metaleny, Peter (-) 2nd Lt, 0-669769	1 Landing	3 - 25	+		FROM			
1	Distachler, Elmer A. 2nd Lt, 0-692954	C C	4 100	li li	+	Godman Fld		14	18
	574th Godman Fld		3:25		1	Jacks	onville	17	: 5
0	Little, Joseph B. S/Sgt 11038778	3	9			MISSION:	121161	-	2
	57kth Godman Fld!	9	3:25		E 100 200	FROM	-	,	. 2
0	Hamos, Salvador (-) Sgt 39289893		3 : 25	+					
0	Foreter William I for 200man Fld J	1	G			TO:			
	Forster, William J. Sgt 33370372 V	SECOND S	3:25	Ber man has m		1			
0	Shupenko, Anthony (-) Sgt 31109362	14	3:25	+-!!-		MISSION.	LANDING		
	578,th Godman Fld V	BERNER F.	1			FROM:			
0	Jenkins, William E. Jr. S/Sgt 33219922	WHICH SHARE SHARE THE PARTY OF	: 25	1 :					
0.	Halpin, William M. Pfc 32449679					10:			
			: 25	1 1 1	:	MISSION:	100.07		
	Accident occurred while taxiing on	-	-	1 1 1 1			LANGUNGS		
	remp after landing.			10月 日日 日日 日日	医 智慧 海田	FROM			88
	any arms annuals.		-	: :	S DEC.	TO			
		-	2				- 1		
	"A THUE EXTRACT COPT"		E MAIN			MISSION	50. 0F		
	0 001	Name of	E-100	100:000 100:00					
	Lossof Fourth	-	<u> </u>			FROM			
	LAFRENCE F. LOSSCH,			li li		TO			
	Captain, Air Corps,		:	1 1	1				
	Operations Officer.					MISSION:	AND OF		
			in in	HECKED:	TRANSCRIB	EO. 17 1	TOTAL		
1 P 1 P 1 P	FLIGHT REPORT . OF	PERATIONS		LEGIBLE AND OPER	TOYAL FLIGHT TIME ENTERS ON FORM 1A	-	FLIGHT	3:	25

FLIGHT REPORT - ENGINEERING

	IN	SPECTION STA	rus	T			SERV	ICINIO						•			
	DATE OF INS		INSPECTED TODAY STATION				(CHE	CK IMMI	LY BEFO	TION OF TAKE-OFF							
DUE BY		By			FUEL (GALLONS)		OIL (QUARTS)								8.9		
PREFLIGHT	12-14-43	1	dman Field	SERVICE	SERV.	IN	N	0. 1	T N	0. 2		2. 3	T		RADIATOR		
DAILY	12-13-43	g Go	dman Field	- S	4CED		SERV.	IN	-	The second lives and the	SERV.	LIN	SERV.	1N	SAD CHE		
ZO HOURS	222:50			:==	-	960	and the Person named in	7 20	-	120	ICED	TANKS	ICED	TANKS	-		
50 HOURS	147:50			2ND							10000						
100 HOURS	197:50			SRD													
				4TH				1000	100						-		
-	MEDECTION	-		STH											-		
EQUIPMENT	SYMBOL	OF AUXILIARY			BTATUS				No	Own	-	Para			_		
	STATE OF THE PERSON NAMED IN	INSPECTED BY	STATION	1.	1	2./	missing on Rt Aux fuel tank.										
BOMBARDMENT				1	1	X	ALL	30. IN	On	HE A	MX I	uel 1	tank.				
GUNNERY				3.	X	4.											
CHEMICAL	INS J	Tombel		1													
COMMUNICATIO		Jenkins	Godman Field					EXCE	PTION	AL RES	LEASE						
PHOTOGRAPHIC			-		WHE	N THE	STATE	US TOO	AY" I	SINDI	CATED	BYAR	N GRA	MBOL.			
NAVIGATION					AIRC	RAFT	WILL S	D ENGI	NEER IS RE	ING OF	FICER.	THEP	ILOT O	FTHE			
						EASED I		1									
DELLA DICE. DI					F	LIGHT		1,							-		
TACK PI	LOTS AND	MECHANIC	S - SEE INSTRUCTIONS INSI	DE FRO	NT COV	ER.			AIRC	RAFT A	ND EN	GINE T	IME RE	CORD			
plane (L	g tip an	d Alleron	Damaged in coll	isio	n wi	th of	ther	DENG	INE	NO. 1	NO	Description	NO S	Section 10	-		
brance (7	o Marers	183.)						HOL TO D	JRS 10	8,25	11	7.15		100 Maria 100 Maria			
(Shunenko	A. Set	- Mante	, C. W. Sat - St					HOL	JRS	3:25		3125			-		
Inspecte	d wing t	ip and Ai	leron and found	sele	, 2.	Sgt,		TOI	THE REAL PROPERTY.	1,50	32	0140			-		
		-P wild all	THE RESIDENCE OF THE PARTY OF T	The second			-	- OIL OH	ANGE	4120	12	2140			-		
			(Shupen	00,	473	(李)		C046. E	STREET, SQUARE,		-		-		-		
			Lawr	and)	7.	500	4	180 5	out t	Mari		1			-		
"A TRUE	EXTRACT	COPYs	LAWRENCE	F.	LOES	SCH.				TO S		11	5:40				
			Captain	Aiz	Co:	TOB.		AIRCE	TAFT	HOU			3125				
			Operatio	ons (offic	oez.			8 i	STATE OF THE PARTY.		133	9:05				
			-							TOT	AL		-7107				
						-											
												-10					
															-		
-se	12				-								-				
	-									-							
															200		
													NAME OF TAXABLE PARTY.				
494	ENGIS	NE DATA	Control Control Control				Marie College		-						- Activities		
E 25 19	19 19	E	AIRGRAF	DATA			AIRCR	AFT O	RG. D	ATA	23						
1 4 F		5 5	=			13		58 8			13		18	13	3		
8 .	2 2 2	32 3	6 16			1		PI	-		R		15				
10 1 1	1 1 1	3131	R I I I I I	2 5		8 =	1	69 9	H	- 40	H	1	5	15	-		
8	1 1	B: B:	I 35 1 0		-	: 8	8	8	103	1 2	13		3 32	. 6			
11 E	1 1	1 0 0	0 0	8		, 是	1	8 8	8	1	F		1 1	a			
6 3	8 8	3 2	F 8	4		8	7	0	8	*	H		- 4				
			1			10	3	8	*		H						
								1		100		1					
The same of the same of	SECTION AND DESCRIPTION AND	Section Section	SHOWING THE RESIDENCE SHOWING		-							1					

ARMY AIR BASE, JACKSONVILLE ARMY AIR FIELD JACKSONVILLE, FLORIDA

14DECEMBER 1943, AT APPROXIMATELY 1845 WHILE TAXING TO PARK ONE B-26 4799, I HIT AND WRECKED TAIL OF B-25 WITH LEFT WING. LIGHTS ON HANGER WERE BLINDING AND THE ALERT MAN WAS FAR AWAY SHOWING PARKING AREA. IT WAS REALLY HARD TO SEE PLANE BECAUSE OF SAID RAMP LIGHTS ON HANGER. ALSO BEING TIRED AFTER FLIGHT THRU CLOUDS IN FORMATION. FRANKLY I SAY I JUST DIDN'T THINK I WAS THAT CLOSE AND WILL ALMOST SWEAR THERE WAS MORE THAN ENOUGH HOOM WITHOUT TAKING CHANGES.

PETER METELSKY, 2nd Lt, Zir Corpe, Godman Field,

Ft Knox, Ky.

14 December 1943

I was riding as CO-pilot on the B-26 which hit the rudder of a B-25 with our wing tip. Coming off the runway we were directed to the ramp by a ground crewman at the corner of the ramp and runway. We could see alright there, but taxiing down the ramp we were blinded on the left from flood lamps above the hangers. We passed and saw a C-46 which was in the flood lamps but the B-25 was underneath the beams light which blacked it out. When we were abseast the C-46, our attention was attracted by a flagman on our right who was directing us into a parking space. In my estimation, he was in a poor position to warn us of any obstructions to our left. We were following this flagmans instruction when I glanced to our left and saw the B-25 about 4 ft from us. I shouted almost instataniously but we were too close for the pilot to prevent the accident even though he acted immediately by applying brakes. In my opinion there should have been another flagman in the vicinity of the B-25 especially since the ship was protruding a great deal further out from the line than the other parked ships.

E. A. DIETSCHIER, 2nd Lt., Air Corps,

INOT PO

14 December 1943.

I was watching the flagman and did not see the B-25 out to our left.

The tow ships in our formation that had landed before us were parked paralled to the runway and the way the flagman was signaling to us he seemed to mean for us to park at right angles to the other ships.

None of us could figure out just how he wanted us to park and all attention seemed to be centered on the flagman.

As the pilot swang around our wing tip caught the left vertical fin of the B-25 and the momenturn carried us clear of the other plane.

The stron lights on top of the hangar were in direct line with the B-25 and may have blinded the pilot as far as his vision to the left was concerned.

JOSEPH R. LITTLE, S/Sgt., AC,

INC ! 18

14 December 1943.

While taxing in for parking our left wing tip crashed into a B-25 vertical stab. Time was 1800, it was dark and flood lights were on, they were very bright and also threw shadows, I didn't even see the B-25. The flagman was motioning us to keep on coming toward him. The Co-pilot while looking around happen to see the B-25 told the Pilot to stop but it was too late.

SALVADOR FRAMOS Sgt., AC, Engineer-Gunner

8gt. Salvador Ramos

100/7 9

ARMY AIR BASE
JACKSONVILLE ARMY AIR FIELD
LACKSONVILLE, FLORIDA
14 DECEMBER 1943

While in route to Mirtle Beach, South Carolina, travelling through very bad weather, forced to land at Jacksonville, Florida, at 1800. While taxing down the ramp to park, we clipped the tail assembly of a B-25 airplane. Blinding lights from the hanger, also poor visibility prevented me from seeing the flagman.

I certify the above statement to be true to the best of my knowledge.

19:913 9. Poster Sps. Wa. J. Forster Radio Gunner

Inc/ #/ 10

ARRY AIR BASE JACKSONVILLE ARRY AIRFIELD JACKSONVILLE, FLORIDA

14th. DECEMBER 1943 SHIP NO. 4799 MY POSITION IN SHIP WAS IN TAIL SECTION.
I CAN SAY VERY LITTLE ABOUT MY TRIP FROM GOODMAN FIELD TO JACKSONVILLE FLORIDA.
A799 TOOK OF AT 1925 FROM GOODMAN FIELD LANDS 1800 AT JACKSONVILLE FIELD FLA.

8/802. W.B. JERRES JR.
578 th. BUR. 59lot. GROUP

GOODMAN FIELD MY.

JM1.21 11

574TH BOMBARDMENT SQUADRON (M) AAF Office of the Operations Officer Godman Field

Fort Knox, Kentucky 20 December 1943

NO CERTAINS ORDERS)

EXIRACI

The following mission was ordered as of this date:

4. 2nd Lt PETER (-) METELSKY, AC, 0-669769, P, in a B-26C ap, AAF No 41-34799, with 2nd Lt ELMER A. DIETSCHLER, AC, 0-692954, CP; S/Sgt JOSEPH R. LITTLE, 11038778, EG, 574th; Sgt WILLIAM J. FORSTER, 33370371, RG, 574th; Sgt SALVADOR (-) RAMOS, 39289899, X, 574th; Sgt ANTHONY (-) SHUPENKO, 31109362, X, 574th, and S/Sgt WILLIAM B. JENKINE, Jr., 33219922, X, 574th, will take off o/a 1450 on a X-C flight to Myrtle Beach Bombing Range, S. C., for the purpose of obtaining gunnery practice.

By order of Major BRANDON:

LAWRENCE F. LOESCH, Captain, Air Corps, Operations Officer.

"A TRUE EXTRACT COPY"

LAWRENCE F. LOESCH, Captain, Air Corps, Operations Officer.

1 mol # 5

HEADQUARTERS ARMY AIR BASE OFFICE OF THE COMMANDING OFFICER

G-RHN/job

6 JAN 1944

2d Lt. AC

Asst Adjutant.

File 360.33

CHATHAM FIELD, GEORGIA.

SUBJECT. Aircraft Accident Report, AAF 62-14

Commending Officer, Headquarters, AAF Office of Flying Safety, Winston-Salem, N C

1. Herewith Forms 14 covering accident of B-26C, AAF Serial Number 41-34799, and B-25D, AAF Serial Number 42-87303, and ellied papers.

2. The above accident occurred at Army Air Base, Jacksonville Army Air Field, Jacksonville, Florida, 14 December 1943.

For the Commanding Officer:

11 Incls. - one (1) oy ea

Incl 1 - AAF Form 14 (B-26C)

Inel 2 - AAF Form 14 (B-25D)

Incl 3 - AAF Form 1

Incl 4 - AAF Form lA

Incl 5 - Operations Orders

Incl 6 - Pilots Statement

Incl 7 - Co-pilots Statements

Incl 8 - Statement of S/Sgt Little

Incl 9 - Statement of Sgt Remos

Inol 10 - Statement of Sgt Forster

Inol 11 - Statement of S/Sgt Jenkins

1